



The service costs are divided into the price of labour and the price of parts. The reason is that the parts may vary in price between different models (for example standard or heavy duty seals)

All drysuit services require a leak test and this is added in the prices

**EXAMPLE:**

Change drysuit zipper, plastic.  
Zipper Change + Plastic Zipper + Leak Testing  
98€ + 99€ + 28€ = 225€

All prices excluding VAT.

| Combined examples:                         | RRP (EUR)    |
|--|--------------|
| Change zipper, plastic zipper              | 288 EUR      |
| Change zipper, metal zipper                | 190 EUR      |
| Change boots or socks, flex soles          | 258 EUR      |
| Change latex neck seal                     | 100 EUR      |
| Change neoprene neck seal                  | 150 EUR      |
| Drysuits                                   | RRP (EUR)    |
| Leak test                                  | 35 EUR       |
| Drysuit cleaning                           | 34 EUR       |
| Change zipper                              | 123 EUR      |
| Arms or Legs Lengthening max 5 cm          | 130 EUR      |
| Leak repair ( per max 3. )                 | 43 EUR       |
| Change attached hood                       | 72 EUR       |
| Change boots or socks                      | 123 EUR      |
| Change latex neck seal                     | 50 EUR       |
| Change neoprene neck seal                  | 79 EUR       |
| Change latex wrist seal                    | 39 EUR       |
| Change neoprene wrist seal                 | 50 EUR       |
| Change face seal on attached hood          | 50 EUR       |
| Change suspenders                          | 43 EUR       |
| Install SiTech wristseal system            | 64 EUR       |
| Install Smart seal system                  | 64 EUR       |
| Install valve                              | 34 EUR       |
| Install neckring                           | 130 EUR      |
| Widening/Narrowing to fit ring system/boot | 64 EUR       |
| Kevlar Knee pad installed / pcs            | 40 EUR       |
| P-valve installed ( excl. P-valve)         | 40 EUR       |
| Arms or legs shortening max 5 cm           | 34 EUR       |
| Repair suspender patch                     | 19 EUR       |
| Seamtape repair (max 1 m)                  | 27 EUR       |
| Sealing boot / pcs                         | 27 EUR       |
| Service Si-Tech drysuit valve              | 17 EUR       |
| Parts                                      | RRP (EUR)    |
| Plastic zipper                             | 130 EUR      |
| Metal zipper                               | 155 EUR      |
| Attached hood - on quote                   | ON QUOTATION |
| Latex neck seal                            | 15 EUR       |
| Latex wrist seal bottleneck                | 4 EUR        |
| Latex - Wrist Seal Bottleneck HD           | 7 EUR        |
| Latex - Wrist Seal Conical                 | 4 EUR        |
| Neoprene - neck seal                       | 36 EUR       |
| Flexsoles                                  | 100 EUR      |
| Teccna boots                               | 130 EUR      |
| Neoprene socks                             | 90 EUR       |
| SI-Tech - exhaust valve servicekit         | 23 EUR       |
| SI-Tech - rotating inlet valve servicekit  | 14 EUR       |
| Warmneck collar                            | 25 EUR       |



| <b>Heating</b>                                       | <b>RRP (EUR)</b> |
|--|------------------|
| Change E/O cord Santi 9 Ah battery                   | 48 EUR           |
| Change E/O cord Santi blue power battery             | 12 EUR           |
| Change connections and cable Santi Thermovalve       | 48 EUR           |
| Change connections and cable Santi heating vest      | 48 EUR           |
| Change connections and cable Santi heating undersuit | 74 EUR           |
| Change connections and cable Santi heating gloves    | 74 EUR           |
| Change E/O cord Ammonite T-valve                     | 48 EUR           |
| Change E/O cord Ammonite battery                     | 64 EUR           |
| <b>Parts</b>   | <b>RRP (EUR)</b> |
| Service kit Santi Connector/Thermovalve              | 19 EUR           |
| E/O cord Santi battery 9ah                           | 50 EUR           |
| E/O cord Blue power                                  | 170 EUR          |
| Service kit Heated vest                              | 38 EUR           |
| Service kit Heated undersuit                         | 44 EUR           |
| Service kit Heated gloves                            | 19 EUR           |
| Service kit Ammonite valve                           | 11 EUR           |
| WAM cable for Ammonite valve                         | 56 EUR           |
| Connection plug Ammonite valve                       | 10 EUR           |
| <b>Regulators</b>                                    | <b>RRP (EUR)</b> |
| Regulator 1st Stage service                          | 45 EUR           |
| Regulator 2nd stage service                          | 52 EUR           |
| Service kit  |                  |
| <b>Suex</b>  | <b>RRP (EUR)</b> |
| Suex maintenance S2                                  | 96 EUR           |
| Suex maintenance S3                                  | 189 EUR          |
| Suex service kit S2                                  |                  |
| Suex service kit S3                                  |                  |
| <b>Other</b>   | <b>RRP (EUR)</b> |
| Labour per hour                                      | 64 EUR           |
| <b>Shearwater</b>                                    | <b>RRP (EUR)</b> |
| Petrel 2 SA  | 159.03           |
| Petrel 2 ext (only fischer)                          | 159.03           |
| Perdix   | 152.19           |
| Perdix 2 natural                                     | 169.77           |
| Perdix 2 black                                       | 174.85           |
| Perdix 2 bronze                                      | 174.85           |
| Teric  | 97.35            |
| Peregrine  | 135.8            |